



Photo 17: Old Adhesive Staining in Basement of Building 2



Photo 18: Residual Adhesive Waste in Tank in Basement of Building 2



Photo 19: Unidentified Waste Drums in Basement of Building 2



Photo 20: Oil Staining on Floor of Second Floor Above Coating Machines in Building 2